

## COVID-19 Jobsite Protocol

All contractors on site are required to wear masks and practice physical distancing with city personnel during inspections. The inspector will make the decision if inspections will take place based upon these requirements.

If a contractor or subcontractor discovers that someone on the jobsite tests positive for the coronavirus, the city of Thornton is to be notified immediately. The person or persons that have tested positive are recommended to be self-quarantined from the jobsite until they test negative. Anyone that was exposed to the person or persons within 5 days prior to the positive test should be tested and if negative can return to work. Those that test positive are recommended to self-quarantine until they test negative.

The general contractor is recommended to do one of the following:

1. Clear the jobsite and quarantine it for 7 days; or,
2. Hire an industrial hygienist to clean the jobsite and certify that it is safe to return to work.

No inspections will be conducted until the city has been notified that the jobsite is safe.